

You Can Buy For Your Lab Scope Today!

FirstLook[™] vacuum waveforms showing the effect of a worn cam and lifter in a Safari van




Note Simple Hookup to Engine



Photo of parts replaced showing cam and roller damage.

Waveforms and photo courtesy of Wilf Breyfogle.





Cam and lifters were replaced. Waveform still shows some effects that engine miss has had on valve seat. With a cleaning and normal running this should return to normal.



784 S. Poseyville Road • Midland, MI 48640

Toll Free: (866) 832-8898 www.senxtech.com

Firstlook[™] and SenX[™] are trademarks of SenX Technology, LLC Midland, Michigan USA Copyright 2002 SenX Technology, LLC Midland, Michigan USA US Patent 6,484,589 Made in the U.S.A.

